# Test Update 771

**Posted Date** 08/04/2021
**Effective Date** 08/03/2021
**Test Name** Lead Profile Occupational Exposure
**Update Type** Test Down or Delayed
**CPT Code** 83655, 84202

**TEST DOWN**

**Lead Profile Occupational Exposure**

**Order Code:** PBZP

**CPT Code:** 83655, 84202

**Referral Laboratory:** Mayo Medical Laboratories

Effective August 3, 2021, Lead Profile Occupational Exposure (PBZP) testing is down due to reagent issues per Mayo Medical Laboratories.

View PDF