



Test Update 771

Posted Date 08/04/2021

Effective Date 08/03/2021

Test Name [Lead Profile Occupational Exposure](#)

Update Type [Test Down or Delayed](#)

CPT Code 83655, 84202

TEST DOWN

Lead Profile Occupational Exposure

Order Code: PBZP

CPT Code: 83655, 84202

Referral Laboratory: Mayo Medical Laboratories

Effective August 3, 2021, Lead Profile Occupational Exposure (PBZP) testing is down due to reagent issues per Mayo Medical Laboratories.

[View PDF](#)