




Test Update 959

Posted Date 06/10/2026

Effective Date 06/08/2026

Test Name [Platelet Transmission Electron Microscopy Study](#)

Update Type [Test Down or Delayed](#)

CPT Code 85390, 88348

TEST DELAY

Platelet Transmission Electron Microscopic Study, Whole Blood

Order Code: PTEM

Fee Code: AA496, AA497 (CPT 85390, 88348)

LOINC: 79768-8

Reference Lab: Mayo PTEM

Effective June 8, 2026, Mayo Clinic Laboratories test, PTEM results are currently delayed beyond the published turnaround time of 12 days due to an increased volume of testing requests. The duration of this delay is expected to exceed 30 days. Specimens are stabilized and processed as they are received.

[View PDF](#)