

Test Update 681

Posted Date 09/04/2019 Effective Date 08/29/2019 Update Type Test Down or Delayed CPT Code 83519 x2

Order Code: DYS2

CPT Code: 83519 x2, 83520, 86255 x2, 86341

Reference Laboratory: Mayo Medical Laboratory

Effective August 29, 2019, Autoimmune Dysautonomia Evaluation, Serum (DYS2) testing may be delayed per Mayo Medical Laboratory due to a reagent issue, potential reflex component ARMO: Acetylcholine Receptor (Muscle AChR) Modulating Antibody, Serum is unable to be performed. As applicable, all pending evaluations will be finalized without the ARMO reflex.

View PDF